

0 LAMBDA SENSOR 31460846 VOLVO 54035-CAG DENSO



Car brand	Volvo
OEM Number	31460846
Manufacturer	Denso
Brand Number	54035-CAG
Available QTY	1130

PRICE: €15.00

PRODUCT DESCRIPTION

VOLVO S60 II (134) 2.0 Polestar AWD

Lambda Sensor
Diagnostic Probe
06.2015 - 05.2018
120525

270
367
1969

Saloon
VOLVO S60 II (134) T3

Lambda Sensor
Diagnostic Probe
03.2015 - 05.2018
113269

112
152
1969

Saloon
VOLVO S60 II (134) T4

Lambda Sensor
Diagnostic Probe
03.2015 - 05.2018
114198

140
190
1969

Saloon
VOLVO S60 II Cross Country (134) T5 AWD

Lambda Sensor
Diagnostic Probe
06.2016 - 12.2018
147926

180
245

1969
Saloon
VOLVO S60 II Cross Country (134) T5 AWD
Lambda Sensor
Diagnostic Probe
06.2016 - 12.2018
147926
180
245
1969
Saloon
VOLVO S60 II Cross Country (134) T5 Drive-E Polestar AWD
Lambda Sensor
Diagnostic Probe
06.2016 - 05.2018
138826
186
253
1969
Saloon
VOLVO S60 II Cross Country (134) T5 Drive-E Polestar AWD
Lambda Sensor
Diagnostic Probe
06.2016 - 05.2018
138826
186
253
1969
Saloon
VOLVO S80 II (124) 2.0 Drive- E
Lambda Sensor
Diagnostic Probe
12.2014 - 12.2016
109981
180
245
1969
Saloon
VOLVO S80 II (124) T5
Lambda Sensor
Diagnostic Probe
01.2014 - 12.2016
120516
162
220
1969
Saloon
VOLVO S80 II (124) T5
Lambda Sensor
Diagnostic Probe
09.2013 - 05.2014
100519
180
245
1969
Saloon
VOLVO V40 Cross Country (526) T3
Lambda Sensor
Diagnostic Probe
04.2015 - 08.2019
147902
112
152
1498
Hatchback
VOLVO V40 Cross Country (526) T4
Lambda Sensor
Diagnostic Probe
08.2015 - 08.2019
147904
140
190
1969
Hatchback
VOLVO V40 Cross Country (526) T5 AWD
Lambda Sensor
Diagnostic Probe
05.2014 - 08.2019
108766
180

245
1969
Hatchback
VOLVO V40 Cross Country (526) T5 AWD
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
05.2014 - 08.2019
108766
180
245
1969
Hatchback
VOLVO V40 Cross Country (526) T5 AWD
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
05.2014 - 08.2019
108766
180
245
1969
Hatchback
VOLVO V40 Cross Country (526) T5 AWD
Lambda Sensor
Diagnostic Probe
05.2014 - 08.2019
108766
180
245
1969
Hatchback
VOLVO V40 Hatchback (525) T2
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
02.2015 - 08.2019
111884
90
122
1498
Hatchback
VOLVO V40 Hatchback (525) T2
Lambda Sensor
Diagnostic Probe
02.2015 - 08.2019
111884
90
122
1498
Hatchback
VOLVO V40 Hatchback (525) T2
Lambda Sensor
Diagnostic Probe
02.2015 - 08.2019
111857
90
122
1969
Hatchback
VOLVO V40 Hatchback (525) T2
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
02.2015 - 08.2019
111857
90
122

1969
Hatchback
VOLVO V40 Hatchback (525) T3
Lambda Sensor
Diagnostic Probe
02.2015 - 08.2019
112556
112
152
1498
Hatchback
VOLVO V40 Hatchback (525) T3
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
02.2015 - 08.2019
112556
112
152
1498
Hatchback
VOLVO V40 Hatchback (525) T3
Lambda Sensor
Diagnostic Probe
02.2015 - 08.2019
111858
112
152
1969
Hatchback
VOLVO V40 Hatchback (525) T3
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
02.2015 - 08.2019
111858
112
152
1969
Hatchback
VOLVO V40 Hatchback (525) T4
Lambda Sensor
Diagnostic Probe
08.2015 - 08.2019
116592
140
190
1969
Hatchback
Description
Model year
TecDoc type no.
kW
HP
cc
Body type
VOLVO V40 Hatchback (525) T5
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
05.2014 - 08.2019
106280
180
245
1969
Hatchback
VOLVO V40 Hatchback (525) T5
Lambda Sensor
Diagnostic Probe
05.2014 - 08.2019
106280

180
245
1969
Hatchback
VOLVO V40 Hatchback (525) T5
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
05.2014 - 08.2019
106280
180
245
1969
Hatchback
VOLVO V40 Hatchback (525) T5
Lambda Sensor
Diagnostic Probe
05.2014 - 08.2019
106280
180
245
1969
Hatchback
VOLVO V40 Hatchback (525) T5 Drive-E Polestar
Lambda Sensor
Diagnostic Probe
05.2014 - 08.2019
138809
186
253
1969
Hatchback
VOLVO V40 Hatchback (525) T5 Drive-E Polestar
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
Lambda Sensor
Diagnostic Probe
05.2014 - 08.2019
138809
186
253
1969
Hatchback
VOLVO V60 I (155) 2.0 Polestar AWD
Lambda Sensor
Diagnostic Probe
06.2015 - 05.2018
120524
270
367
1969
Estate
VOLVO V60 I (155) T6 AWD
Lambda Sensor
Diagnostic Probe
10.2013 - 12.2018
117791
225
306
1969
Estate
VOLVO V60 I Cross Country (157) T5
Lambda Sensor
Diagnostic Probe
03.2015 - 05.2018
147937
180
245
1969
Estate
VOLVO V60 I Cross Country (157) T5
Lambda Sensor
Diagnostic Probe
03.2015 - 05.2018
147937

180
245
1969
Estate
VOLVO V60 I Cross Country (157) T5 AWD
Lambda Sensor
Diagnostic Probe
06.2016 - 05.2018
147938

180
245
1969
Estate
VOLVO V60 I Cross Country (157) T5 Drive-E Polestar AWD
Lambda Sensor
Diagnostic Probe
03.2015 - 07.2018
138816

186
253
1969
Estate
VOLVO V70 III (135) T4
Lambda Sensor
Diagnostic Probe
03.2015 - 04.2016
113284

140
190
1969
Estate
VOLVO XC40 (536) T5 AWD
Lambda Sensor
Diagnostic Probe
10.2017 - 09.2021
128759

182
247
1969
SUV
VOLVO XC40 (536) T5 AWD
Lambda Sensor
Diagnostic Probe
10.2017 -
134183

184
250
1969
SUV
VOLVO XC40 (536) T5 AWD
Lambda Sensor
Diagnostic Probe
10.2017 -
134183

184
250
1969
SUV
VOLVO XC40 (536) T5 Polestar AWD
Lambda Sensor
Diagnostic Probe
10.2017 - 09.2019
138718

183
249
1969
SUV
VOLVO XC60 I SUV (156) T5 AWD
Lambda Sensor
Diagnostic Probe
10.2015 - 02.2017
119578

180
245
1969
SUV
VOLVO XC60 I SUV (156) T6 AWD
Lambda Sensor
Diagnostic Probe
10.2013 - 12.2017

117792

225

306

1969

SUV

VOLVO XC60 I SUV (156) T6 AWD

Lambda Sensor

Diagnostic Probe

10.2013 - 12.2017

117792

225

306

1969

SUV