

0 LAMBDA SENSOR 31460846 VOLVO 54035-CAG DENSO



Car brand	Volvo
OEM Number	31460846
Manufacturer	Denso
Brand Number	54035-CAG
Available QTY	1140

PRICE: €15.00

PRODUCT DESCRIPTION

VOLVO S60 II (134) 2.0 Polestar AWD

Lambda Sensor  
Diagnostic Probe  
06.2015 - 05.2018  
120525

270  
367  
1969

Saloon  
VOLVO S60 II (134) T3

Lambda Sensor  
Diagnostic Probe  
03.2015 - 05.2018  
113269

112  
152  
1969

Saloon  
VOLVO S60 II (134) T4

Lambda Sensor  
Diagnostic Probe  
03.2015 - 05.2018  
114198

140  
190  
1969

Saloon  
VOLVO S60 II Cross Country (134) T5 AWD

Lambda Sensor  
Diagnostic Probe  
06.2016 - 12.2018  
147926

180  
245

1969  
Saloon  
VOLVO S60 II Cross Country (134) T5 AWD  
Lambda Sensor  
Diagnostic Probe  
06.2016 - 12.2018  
147926  
180  
245  
1969  
Saloon  
VOLVO S60 II Cross Country (134) T5 Drive-E Polestar AWD  
Lambda Sensor  
Diagnostic Probe  
06.2016 - 05.2018  
138826  
186  
253  
1969  
Saloon  
VOLVO S60 II Cross Country (134) T5 Drive-E Polestar AWD  
Lambda Sensor  
Diagnostic Probe  
06.2016 - 05.2018  
138826  
186  
253  
1969  
Saloon  
VOLVO S80 II (124) 2.0 Drive- E  
Lambda Sensor  
Diagnostic Probe  
12.2014 - 12.2016  
109981  
180  
245  
1969  
Saloon  
VOLVO S80 II (124) T5  
Lambda Sensor  
Diagnostic Probe  
01.2014 - 12.2016  
120516  
162  
220  
1969  
Saloon  
VOLVO S80 II (124) T5  
Lambda Sensor  
Diagnostic Probe  
09.2013 - 05.2014  
100519  
180  
245  
1969  
Saloon  
VOLVO V40 Cross Country (526) T3  
Lambda Sensor  
Diagnostic Probe  
04.2015 - 08.2019  
147902  
112  
152  
1498  
Hatchback  
VOLVO V40 Cross Country (526) T4  
Lambda Sensor  
Diagnostic Probe  
08.2015 - 08.2019  
147904  
140  
190  
1969  
Hatchback  
VOLVO V40 Cross Country (526) T5 AWD  
Lambda Sensor  
Diagnostic Probe  
05.2014 - 08.2019  
108766  
180

245  
1969  
Hatchback  
VOLVO V40 Cross Country (526) T5 AWD  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
05.2014 - 08.2019  
108766  
180  
245  
1969  
Hatchback  
VOLVO V40 Cross Country (526) T5 AWD  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
05.2014 - 08.2019  
108766  
180  
245  
1969  
Hatchback  
VOLVO V40 Cross Country (526) T5 AWD  
Lambda Sensor  
Diagnostic Probe  
05.2014 - 08.2019  
108766  
180  
245  
1969  
Hatchback  
VOLVO V40 Hatchback (525) T2  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
02.2015 - 08.2019  
111884  
90  
122  
1498  
Hatchback  
VOLVO V40 Hatchback (525) T2  
Lambda Sensor  
Diagnostic Probe  
02.2015 - 08.2019  
111884  
90  
122  
1498  
Hatchback  
VOLVO V40 Hatchback (525) T2  
Lambda Sensor  
Diagnostic Probe  
02.2015 - 08.2019  
111857  
90  
122  
1969  
Hatchback  
VOLVO V40 Hatchback (525) T2  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
02.2015 - 08.2019  
111857  
90  
122

1969  
Hatchback  
VOLVO V40 Hatchback (525) T3  
Lambda Sensor  
Diagnostic Probe  
02.2015 - 08.2019  
112556  
112  
152  
1498  
Hatchback  
VOLVO V40 Hatchback (525) T3  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
02.2015 - 08.2019  
112556  
112  
152  
1498  
Hatchback  
VOLVO V40 Hatchback (525) T3  
Lambda Sensor  
Diagnostic Probe  
02.2015 - 08.2019  
111858  
112  
152  
1969  
Hatchback  
VOLVO V40 Hatchback (525) T3  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
02.2015 - 08.2019  
111858  
112  
152  
1969  
Hatchback  
VOLVO V40 Hatchback (525) T4  
Lambda Sensor  
Diagnostic Probe  
08.2015 - 08.2019  
116592  
140  
190  
1969  
Hatchback  
Description  
Model year  
TecDoc type no.  
kW  
HP  
cc  
Body type  
VOLVO V40 Hatchback (525) T5  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
05.2014 - 08.2019  
106280  
180  
245  
1969  
Hatchback  
VOLVO V40 Hatchback (525) T5  
Lambda Sensor  
Diagnostic Probe  
05.2014 - 08.2019  
106280

180  
245  
1969  
Hatchback  
VOLVO V40 Hatchback (525) T5  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
05.2014 - 08.2019  
106280  
180  
245  
1969  
Hatchback  
VOLVO V40 Hatchback (525) T5  
Lambda Sensor  
Diagnostic Probe  
05.2014 - 08.2019  
106280  
180  
245  
1969  
Hatchback  
VOLVO V40 Hatchback (525) T5 Drive-E Polestar  
Lambda Sensor  
Diagnostic Probe  
05.2014 - 08.2019  
138809  
186  
253  
1969  
Hatchback  
VOLVO V40 Hatchback (525) T5 Drive-E Polestar  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
Lambda Sensor  
Diagnostic Probe  
05.2014 - 08.2019  
138809  
186  
253  
1969  
Hatchback  
VOLVO V60 I (155) 2.0 Polestar AWD  
Lambda Sensor  
Diagnostic Probe  
06.2015 - 05.2018  
120524  
270  
367  
1969  
Estate  
VOLVO V60 I (155) T6 AWD  
Lambda Sensor  
Diagnostic Probe  
10.2013 - 12.2018  
117791  
225  
306  
1969  
Estate  
VOLVO V60 I Cross Country (157) T5  
Lambda Sensor  
Diagnostic Probe  
03.2015 - 05.2018  
147937  
180  
245  
1969  
Estate  
VOLVO V60 I Cross Country (157) T5  
Lambda Sensor  
Diagnostic Probe  
03.2015 - 05.2018  
147937

180  
245  
1969  
Estate  
VOLVO V60 I Cross Country (157) T5 AWD  
Lambda Sensor  
Diagnostic Probe  
06.2016 - 05.2018  
147938  
180  
245  
1969

Estate  
VOLVO V60 I Cross Country (157) T5 Drive-E Polestar AWD  
Lambda Sensor  
Diagnostic Probe  
03.2015 - 07.2018  
138816  
186  
253  
1969

Estate  
VOLVO V70 III (135) T4  
Lambda Sensor  
Diagnostic Probe  
03.2015 - 04.2016  
113284  
140  
190  
1969

Estate  
VOLVO XC40 (536) T5 AWD  
Lambda Sensor  
Diagnostic Probe  
10.2017 - 09.2021  
128759  
182  
247  
1969

SUV  
VOLVO XC40 (536) T5 AWD  
Lambda Sensor  
Diagnostic Probe  
10.2017 -  
134183  
184  
250  
1969

SUV  
VOLVO XC40 (536) T5 AWD  
Lambda Sensor  
Diagnostic Probe  
10.2017 -  
134183  
184  
250  
1969

SUV  
VOLVO XC40 (536) T5 Polestar AWD  
Lambda Sensor  
Diagnostic Probe  
10.2017 - 09.2019  
138718  
183  
249  
1969

SUV  
VOLVO XC60 I SUV (156) T5 AWD  
Lambda Sensor  
Diagnostic Probe  
10.2015 - 02.2017  
119578  
180  
245  
1969

SUV  
VOLVO XC60 I SUV (156) T6 AWD  
Lambda Sensor  
Diagnostic Probe  
10.2013 - 12.2017

117792

225

306

1969

SUV

VOLVO XC60 I SUV (156) T6 AWD

Lambda Sensor

Diagnostic Probe

10.2013 - 12.2017

117792

225

306

1969

SUV